


# COBRA

Dry Screw Vacuum Pumps NS 0070 C, NS 0160 C Semicon

### **Instruction Manual**





C€ ヒĂ EÆ

## **Table of Contents**

1	Safet	/	4			
2	Prod	ct Description	5			
	2.1	Operating Principle	7			
	2.2	Intended Use	7			
	2.3	Start Controls	8			
	2.4	Standard Features	8			
		2.4.1 Water Cooling	8			
		2.4.2 Sealing Systems	8			
	2.5	Optional Accessories	8			
		2.5.1 Silencer	8			
		2.5.2 Barrier Gas System	8			
		2.5.3 Dilution Gas System	8			
		<ul><li>2.5.4 Purge Gas System</li><li>2.5.5 Resistance Thermometer</li></ul>	9 9			
		2.5.6 Temperature Switch (TS)	9			
		2.5.7 Cooling Water Flowmeter (CWM)	9			
		2.5.8 Nitrogen Flowmeter (FME)	9			
3	Trans	port	10			
4		ge	11			
5	Insta	lation	12			
	5.1	Installation Conditions	12			
	5.2	Connecting Lines / Pipes	12			
		5.2.1 Suction Connection	13			
		5.2.2 Discharge Connection	13			
		5.2.3 Cooling Water Connection	14			
		<ul><li>5.2.4 Barrier Gas System Connection (Optional)</li><li>5.2.5 Dilution Gas System Connection (Optional)</li></ul>	16 17			
	БЭ					
	5.3	Filling Oil	18			
	5.4	Filling Cooling Liquid	20			
6		ical Connection				
	6.1					
	6.2	Wiring Diagram Three-Phase Motor (Pump Drive)	22			
7	Com	nissioning	25			
8	Main	enance	27			
	8.1	Maintenance Schedule	28			
	8.2	Oil Level Inspection	28			
	8.3	Oil Color Inspection	28			
	8.4	Cooling Liquid Level Inspection	29			
	8.5	Oil Change	29			
	8.6	Cooling Liquid Change	32			
9		aul	33			
9 10		nmissioning	34			
	10.1	Dismantling and Disposal	34			
11	Spare	Parts	35			
12	•	leshooting	36			
13	Tech	ical Data	38			

14	Cooling Liquid	39
15	Oil	40
16	EU Declaration of Conformity	41
17	UK Declaration of Conformity	42



## Safety

Prior to handling the machine, this instruction manual should be read and understood. If anything needs to be clarified, please contact your Busch representative.

Read this manual carefully before use and keep for future reference.

This instruction manual remains valid as long as the customer does not change anything on the product.

The machine is intended for industrial use. It must be handled only by technically trained personnel.

Always wear appropriate personal protective equipment in accordance with the local regulations.

The machine has been designed and manufactured in accordance with the state-of-the-art methods. Nevertheless, residual risks may remain, as described in the following chapters and in accordance with the chapter *Intended Use* [ $\rightarrow$  7].

This instruction manual highlights potential hazards where appropriate. Safety notes and warning messages are tagged with one of the keywords DANGER, WARNING, CAUTION, NOTICE and NOTE as follows:

# 

... indicates an imminent dangerous situation that will result in death or serious injuries if not prevented.

# 

... indicates a potentially dangerous situation that could result in death or serious injuries.

# 

... indicates a potentially dangerous situation that could result in minor injuries.




... indicates a potentially dangerous situation that could result in damage to property.




... indicates helpful tips and recommendations, as well as information for efficient and trouble-free operation.

2 **Product Description** 



Description					
DGC	Dilution gas connection	CLD	Cooling liquid drain plug		
CLF	Cooling liquid filler plug	CLG	Cooling liquid sight glass		
CWI 1	Cooling water inlet	CWO 1	Cooling water outlet		
CWI 2	Cooling water inlet	CWO 2	Cooling water outlet		
IN	Suction connection	MP	Magnetic plug		
MTB	Motor terminal box	NP	Nameplate		
OFP 1	Oil filler plug	OFP 2	Oil filler plug		
ODP 1	Oil drain plug	ODP 2	Oil drain plug		
OSG 1	Oil sight glass	OSG 2	Oil sight glass		
OUT	Discharge connection	TV	Thermostatic valve		
PMR	Plug for manual rotation of rotors				

Instruction Manual COBRA NS 0070-0160 C Semicon\_EN\_en



#### P&ID "Piping and Instrumentation Diagram"

Description				
1	Process gas inlet	2	Process gas outlet	
3	Nitrogen supply	4	Cooling water inlet	
5	Cooling water outlet	6	Motor DP (MOT 1)	
7	Oil sight glass (OSG 1)	8	Oil sight glass (OSG 2)	
9	Thermostatic valve (TV)			

#### ο **ΝΟΤΕ**

#### Technical term.


In this instruction manual, we consider that the term 'machine' refers to the 'vacuum pump'.



#### Illustrations.

In this instruction manual, the illustrations may differ from the appearance of the machine.

### 2.1 Operating Principle



The machine works on the one-stage, twin-screw pump principle.

Two screw rotors rotate inside the cylinder. The pumped medium is trapped between the cylinder and screw chambers, compressed, and transported to the gas outlet. During the compression process, the two screw rotors do not come into contact with each other or with the cylinder. There is no need for a lubrication or an operating fluid in the compression chamber.

### 2.2 Intended Use



In case of foreseeable misuse outside the intended use of the machine.

**Risk of injuries!** 

Risk of damage to the machine!

Risk of damage to the environment!

• Make sure to follow all instructions described in this manual.

Conveying of other media leads to an increased thermal and/or mechanical load on the machine and is permissible only after a consultation with Busch.

The machine is intended for the placement in a non-potentially explosive environment.

The machine is capable of maintaining ultimate pressure, see Technical Data.

Permitted environmental conditions, see Technical Data.

## NOTICE

Chemical compatibility of the process gases with the machine component materials.

Risk of corrosion inside the compression chamber which can reduce performance and its lifetime!

- Check if the process gases are compatible with those following materials:
  - Ductile cast iron
  - Nickel
  - Polytetrafluoroethylene (PTFE)
  - Steel
  - Stainless Steel
  - Fluor elastomer (FKM/FPM)
- In doubt, please contact your Busch representative.

Solid particles must not get into the vacuum pump. Procedural errors can result in the pump sucking in a certain quantity of liquid. If the pump has sucked in liquid, a short drying time is necessary at the end of the process.

### 2.3 Start Controls

The machine comes without start controls. The control of the machine is to be provided in the course of installation.

### 2.4 Standard Features

### 2.4.1 Water Cooling

The machine is cooled by an internal, closed cooling liquid circuit in the cylinder cover and cylinder.

Cooling water is cooling the cooling liquid, the motor and the gearbox. The cooling water flow for the motor cooling is factory set on 2.5 l/min.

The thermostatic valve (TV) allows a temperature regulation of the machine by regulating the cooling water flow.

The adjustment of thermostatic valve from position 1 (cool position) to the position 5 (hot position) alters the cooling water temperature and must correspond to the application requirements.

# 

#### Busch recommendations for the thermostatic valve adjustment:

- The position 1 (cold position) is mainly intended for applications with a risk of polymerization.
- The position 5 (hot position) is mainly intended for applications with a risk of condensation .

As standard, the vacuum pump is delivered without water temperature control device.

• Regularly check the temperature of the cooling water. Too high temperature of the cooling water will not make it possible to regulate the cooling liquid temperature.

### 2.4.2 Sealing Systems

The machine is equipped with labyrinth seals on the motor side and suction side.

Sealing systems prevent the process gas going to the bearings chambers.

Depending on the application, the sealing systems efficiency can be improved with a barrier gas system, see *Barrier Gas System* [ $\rightarrow$  8].

### 2.5 **Optional Accessories**

#### 2.5.1 Silencer

A silencer at the discharge connection (OUT) can be provided to reduce the exhaust gas noise.

#### 2.5.2 Barrier Gas System

The barrier gas system allows the supply of compressed air or nitrogen into the motor side shaft seals to improve the sealing efficiency.

### 2.5.3 Dilution Gas System

The dilution gas system prevents the formation of condensates or dilutes them. The nitrogen is fed directly into the cylinder.

### 2.5.4 Purge Gas System

The purge gas system fitted to the inlet flange allows to flush the machine after use or during operation. This system consists of a solenoid valve which enables to open and close the purge circuit. The filtered gas is fed directly into the inlet flange.

### 2.5.5 Resistance Thermometer

The resistance thermometer monitors the cooling liquid temperature of the machine.

A trip signal must be set. The machine must be stopped when the cooling liquid temperature reaches 100°C.

### 2.5.6 Temperature Switch (TS)

The temperature switch monitors the cooling liquid temperature of the machine.

A trip signal must be set. The machine must be stopped when the cooling liquid temperature reaches 100°C.

### 2.5.7 Cooling Water Flowmeter (CWM)

The flow of the cooling water is checked by the flowmeter CWM.

The flowmeter must be connected in such a way that switching-on leads to an alarm and stopping of the vacuum pump when the flow drops below 2 l/min.

### 2.5.8 Nitrogen Flowmeter (FME)

The flow nitrogen is checked by the flowmeter (FME).

The flowmeter must be connected in such a way that switching-on leads to an alarm.

The alarm limit can be adjusted depending on the type of process.

3

## Transport



## 

Suspended load.

Risk of severe injury!

• Do not walk, stand, or work under suspended loads.



## 

Lifting the machine using the motor eye bolt.

Risk of severe injury!


• Do not lift the machine using the eye bolt fitted to the motor. Only lift the machine as shown.



In case the machine is already filled with oil.

Tilting a machine that is already filled with oil can cause large quantities of oil to ingress into the cylinder.

- Drain the oil prior to every transport or always horizontally transport the machine.
- To find out the weight of the machine, refer to the chapter Technical Data or the nameplate (NP).
- Make sure that the eye bolt(s) (EB) is/are in faultless condition, fully screwed in and tightened by hand.



• Check the machine for transport damage.

If the machine is secured to a base plate:

• Remove the machine from the base plate.

## 4 Storage

• Seal all apertures with adhesive tape or reuse provided caps.

If the machine is to be stored for more than 3 months:

- Wrap the machine in a corrosion inhibiting film.
- Store the machine indoors, in a dry and dust free environment and if possible, in original packaging, preferably at temperatures between 5 ... 50 °C.

## 5 Installation

### 5.1 Installation Conditions

## 

Use of the machine outside of the permitted installation conditions.

#### Risk of premature failure!

#### Loss of efficiency!

- Make sure that the installation conditions are fully respected.
- Make sure that the environment of the machine is not potentially explosive.
- Make sure that the ambient conditions comply with the Technical Data.
- Make sure that the environmental conditions comply with the protection class of the motor and the electrical elements.
- Make sure that the installation space or location is vented such that sufficient cooling of the machine is provided.
- Make sure that the oil sight glass (OSG) remains easily visible.
- Make sure that enough space remains for maintenance work.
- Make sure that the machine is placed or mounted horizontally, a maximum deviation of 1° in any direction is acceptable.
- Check the oil level, see Oil Level Inspection [ $\rightarrow$  28].
- Check the cooling liquid level, see *Cooling Liquid Level Inspection* [ $\rightarrow$  29].
- Make sure that the cooling water complies with the requirements, see Cooling Water Connection.

### 5.2 Connecting Lines / Pipes

- Remove all protective covers before installation.
- Make sure that the connection lines cause no stress on the connections of the machine. Therefore, we recommend installing flexible lines on the suction and discharge connections.
- Make sure that the diameter of the connection lines over the entire length is at least as large as the connections of the machine.

In case of long connection lines, it is recommended to use larger diameters to avoid a loss of efficiency. In case, contact your Busch representative.

### 5.2.1 Suction Connection

# WARNING

Unprotected suction connection.

#### **Risk of severe injury!**

• Do not put hand or fingers in the suction connection.

## NOTICE

#### Ingress of foreign objects or liquids.

#### Risk of damage to the machine !

If the inlet gas contains dust or other foreign solid particles:

• Install a suitable filter (5 micron or less) upstream from the machine.

Connection size(s):

- DN40 for NS 0070-0160 C

If the machine is used as part of a vacuum system:

- Busch recommends the installation of an isolation valve in order to prevent the machine from turning backwards.
- Make sure that the connection lines cause no stress on the connections of the machine. Therefore, we recommend installing flexible lines on the suction and discharge connections.

### 5.2.2 Discharge Connection



Unprotected discharge connection.

#### **Risk of severe injury!**

• Do not put hand or fingers in the discharge connection.

## 

#### Discharge gas flow obstructed.


Risk of damage to the machine !

• Make sure that the discharged gas will flow without obstruction. Do not shut off or throttle the discharge line or use it as a pressurized air source.

Connection size(s):

- DN40 for NS 0070-0160 C
- Make sure that the connection lines cause no stress on the connections of the machine. Therefore, we recommend installing flexible lines on the suction and discharge connections.
- Make sure that the counter pressure (also called "back pressure") at the discharge connection (OUT) does not exceed the maximum allowable discharge pressure, see Technical Data.

### 5.2.3 Cooling Water Connection



Description				
CWI 1	Cooling water inlet	CWI 2	Cooling water inlet	
CWO 1	Cooling water outlet	CWO 2	Cooling water outlet	
TV	Thermostatic valve			

# 

The thermostatic valve (TV) allows a temperature regulation of the machine by regulating the cooling water flow.

#### Risk of damage to the machine!

#### Busch recommendations for the thermostatic valve adjustment:

- The position 1 (cold position) is mainly intended for applications with a risk of polymerization.
- The position 5 (hot position) is mainly intended for applications with a risk of condensation.
- Do not go directly from position 5 to position 1, or vice versa. The transition from position 5 to position 1, or vice versa, must be done in stages.
- Allow the vacuum pump to stabilize between each position change (15 minutes).
- For optimal adjustment position of the thermostatic valve, seek advice from your Busch representative.
- Connect the cooling water connections (CWI / CWO) to the water supply.
- Make sure that the cooling water complies with the following requirements:

Supply capacity	l/min	3 - 4
Water pressure	bar (g)	2 5
Supply temperature	°C	+10 +20
Required pressure differential across supply and return	bar (g)	≥ 2

• To reduce the maintenance effort and ensure a long product lifetime, we recommend the following cooling water quality:


Hardness	mg/l (ppm)	< 90	
Properties	Clean & clear		
PH value	7 9	79	
Particle size	μm	< 200	
Chloride	mg/l	< 100	
Electrical conductivity	μS/cm	≤ 100	
Free chloride	mg/l	< 0.3	
Materials in contact with the cooling water	Stainless stee	el, copper	

# <u>ຼິ</u> NOTE

Water hardness unit conversion.

1 mg/l (ppm) = 0.056 °dh (german degree) = 0.07 °e (english degree) = 0.1 °fH (french degree)

### 5.2.4 Barrier Gas System Connection (Optional)




### Description

BGC Barrier gas connection (x 2)

- Connect the barrier gas connection (BGC) to the gas supply.
- Make sure that the gas complies with the following requirements:

Gas type	Dry nitrogen or air	
Gas temperature	°C	0 60
Recommended pressure setting at the pres- sure regulating valve (PRV)	bar (g)	1.5
Filtration	μm	5
Recommended flow rate	SLM (standard li- ter per minute)	8 - 10

### 5.2.5 Dilution Gas System Connection (Optional)



Descript	ion	
DGC	Dilution gas connection (x 2)	

- Connect the dilution gas connection (DGC) to the gas supply.
- Make sure that the gas complies with the following requirements:

Gas type	Dry nitrogen	
Gas temperature	°C	0 60
Recommended pressure setting at the pres- sure regulating valve (PRV)	bar (g)	1.5 3.0
Filtration	μm	5
Recommended flow rate	SLM (standard li- ter per minute)	18 (depends on process)

### 5.3

## **Filling Oil**

## 


Use of an inappropriate oil.


Risk of premature failure!

Loss of efficiency!

• Only use an oil type which has previously been approved and recommended by Busch.

For oil type and oil capacity see Technical Data and *Oil* [ $\rightarrow$  40].





When the oil filling is achieved:

• Write down the oil change date on the sticker.




If there is no sticker (part no. 0565 568 959) on the machine:

• Order it from your Busch representative.

### 5.4 Filling Cooling Liquid

For cooling liquid type and cooling liquid capacity see Technical Data and *Cooling Liquid* [ $\rightarrow$  39].



6

### **Electrical Connection**



## DANGER

Live wires.

**Risk of electrical shock!** 

• Electrical installation work must only be executed by qualified personnel.

#### CURRENT PROTECTION OF THE CUSTOMER INSTALLATION:



## A DANGER

Missing current protection.

#### **Risk of electrical shock!**

- Current protection in accordance with EN 60204-1 must be provided by the customers on their installation(s).
- The electrical installation must comply with the applicable national and international standards.

## 

#### Electromagnetic compatibility.

- Make sure that the motor of the machine will not be affected by electric or electromagnetic disturbance from the mains, if necessary, seek advice from Busch.
- Make sure that the EMC of the machine is compliant with the requirements of your supply network system, if necessary, provide further interference suppression (EMC of the machine, see EU Declaration of Conformity [→ 41] or UK Declaration of Conformity [→ 42]).


# 

The operating rotational speed of the drive motor must correspond to the pump's nameplate value. Do not exceed the mentioned rotational speed.

n<sub>max</sub> = 3000 min<sup>-1</sup> -> 50Hz

n<sub>max</sub> = 3600 min<sup>-1</sup> -> 60Hz

Risk of damage to the vacuum pump!



### 6.1 Machine delivered without Control Box or Variable Speed Drive (VSD)



## DANGER

Live wires.

#### Risk of electrical shock.

- Electrical installation work must only be executed by qualified personnel.
- Make sure that the power supply for the motor is compatible with the data on the nameplate of the motor.
- Provide an overload protection according to EN 60204-1 for the motor.
- Connect the protective earth conductor.
- Electrically connect the motor.



#### The motor frequency is below 20 Hz.

#### Risk of damage to the machine!

• The motor nominal speed must always be higher than 1200 min<sup>-1</sup> (20 Hz).

**NOTICE** 

Incorrect connection.


#### Risk of damage to the motor!

• The wiring diagrams given below are typical. Check the inside of the terminal box for motor connection instructions/diagrams.

6.2

### Wiring Diagram Three-Phase Motor (Pump Drive)


Motor connectors:




Connection of motor temperature switch (recommended):



Only apply voltages ≤ 250 VAC Max. current: 1.6 A MTS = Motor temperature switch (in motor coil) Delta connection (low voltage):



Star connection (high voltage):



The tightening torque does not comply with the recommendation.

Risk of damage the connector threads!

• When connecting up the wires into the terminal box, make sure the tightening torque of 3 Nm is applied and checked with a calibrated torque wrench.




#### Incorrect direction of rotation.

#### Risk of damage to the machine!

• Operation in the wrong direction of rotation can destroy the machine in a short time! Prior to start-up, ensure that the machine is operated in the right direction.

The intended rotation direction of the motor is defined by the illustration below:



- Jog the motor briefly.
- With a phase rotation tester, check if the wiring corresponds to the correct direction of rotation.

If the rotation of the motor must be changed:

• Switch any two of the motor phase wires.

7

## Commissioning



### 

During operation the surface of the machine may reach temperatures of more than 70°C.

#### Risk of burns!

• Avoid contact with the machine during and directly after operation.

# 



#### Noise of running machine. Risk of damage to hearing!

If people are present in the vicinity of a machine that is not insulated from noise for extended periods of time:

• Make sure to wear hearing protection.

## 

The machine can be shipped without oil.

Operation without oil will ruin the machine in short time!

• Prior to commissioning, the machine must be filled with oil, see *Filling Oil* [→ 18].

# 

The machine can be shipped without cooling liquid.

#### Operation without cooling liquid will ruin the machine in short time!

Prior to commissioning, the machine must be filled with cooling liquid, see *Filling Cooling Liquid*[→ 20].

## 

Lubricating a dry running machine (compression chamber).

#### Risk of damage to the machine!

- Do not lubricate the compression chamber of the machine with oil or grease.
- Make sure that the Installation Conditions  $[\rightarrow 12]$  are met.
- Turn on the water supply.

Make sure that the machine does not contain a potentially explosive atmosphere. In case of doubt, the machine must be purged by an inert gas.

- Turn on the barrier gas supply.
- Start the machine.
- Make sure that the maximum permissible number of starts does not exceed 6 starts per hour. Those starts should be spread within the hour.

- Make sure that the operating conditions comply with the Technical Data.
- After a few minutes of operation, perform an *Oil Level Inspection*  $[\rightarrow 28]$ .
- After a few minutes of operation, perform a *Cooling Liquid Level Inspection* [ $\rightarrow$  29].

As soon as the machine is operated under normal operating conditions:

• Measure the motor current and record it as reference for future maintenance and troubleshooting work.

### 8

### Maintenance



## DANGER

Live wires.

**Risk of electrical shock!** 

• Electrical installation work must only be executed by qualified personnel.



## 🔨 WARNING

The machine is contaminated with hazardous material.

Risk of poisoning!

**Risk of infection!** 

If the machine is contaminated with hazardous material:

• Wear appropriate personal protective equipment.



## 

#### Hot surface.

#### **Risk of burns!**

• Before doing anything that requires touching the machine, let it cool down first.



Failing to properly maintain the machine.

**Risk of injuries!** 

#### Risk of premature failure and loss of efficiency!

- Maintenance work must only be executed by qualified personnel.
- Respect the maintenance intervals or ask your Busch representative for service.

## 

#### Using inappropriate cleaners.

#### Risk of removing safety stickers and protective paint!

- Do not use incompatible solvents to clean the machine.
- Shut down the machine and lock against inadvertent start up.
- Turn off the water supply.
- Vent the connected lines to atmospheric pressure.

If necessary:

• Disconnect all connections.

### 8.1 Maintenance Schedule

The maintenance intervals depend very much on the individual operating conditions. The intervals given below are considered as starting values which should be individually shortened or extended as appropriate.

Particularly harsh applications or heavy duty operation, such as high dust loads in the environment or in the process gas, other contamination or ingress of process material, can make it necessary to shorten the maintenance intervals significantly.

Interval	Maintenance work
Monthly	• Check the oil level, see Oil Level Inspection [ $\rightarrow$ 28].
	<ul> <li>Check the cooling liquid level, see Cooling Liquid Level In- spection [→ 29].</li> </ul>
	• Check the machine for oil leaks. In case of leaks, have the machine repaired (Contact Busch).
Yearly	• Carry out a visual inspection and clean the machine from dust and dirt
	• Check the electrical connections and the monitoring devices.
	<ul> <li>Change the cooling liquid, see <i>Cooling Liquid Change</i></li> <li>[→ 32].</li> </ul>
	• Clean the magnetic plugs (MP).
Every 16000 hours or after 4 years	<ul> <li>Change the oil of the gear and bearing housings (both sides), see Oil Change [→ 29].</li> </ul>
	• Have a major overhaul on the machine (contact Busch).

### 8.2

### **Oil Level Inspection**

- Shut down the machine.
- When the machine is stopped, wait 1 minute before checking the oil level.



• Fill up if necessary, see Oil Filling [ $\rightarrow$  18].

### 8.3

### **Oil Color Inspection**



### WARNING

#### Oil "YLC 250 B" contaminated chemically or by foreign bodies.

#### **Risk of explosion!**

If the oil becomes dark:

- Contact your Busch representative without delay.
- Make sure that the oil is either light or transparent.

If the oil becomes dark or looks different from the initial color:


• Change the oil immediately, see Oil Change [ $\rightarrow$  29].



You can consult your Busch representative in order to find out why this color change has occurred.

### 8.4 Cooling Liquid Level Inspection

- Shut down the machine.
- Let the machine cool down.



• Fill up if necessary, see Filling Cooling Liquid [ $\rightarrow$  20].

### 8.5 Oil Change


## 

Use of an inappropriate oil.


Risk of premature failure!

Loss of efficiency!

• Only use an oil type which has previously been approved and recommended by Busch.



For oil type and oil capacity see Technical Data and *Oil* [ $\rightarrow$  40].



When the oil filling is achieved:


• Write down the oil change date on the sticker.




If there is no sticker (part no. 0565 568 959) on the machine:

• Order it from your Busch representative.





For cooling liquid type and cooling liquid capacity see Technical Data and *Cooling Liquid* [ $\rightarrow$  39].



## Overhaul



9





The machine is contaminated with hazardous material.

#### Risk of poisoning!

#### **Risk of infection!**

If the machine is contaminated with hazardous material:

• Wear appropriate personal protective equipment.

## 

Improper assembly.

#### Risk of premature failure!

Loss of efficiency!

• Any dismantling of the machine that goes beyond anything that is described in this manual should be done by Busch authorized technicians.

If the machine has conveyed gas contaminated with foreign materials which are hazardous to health:

• Decontaminate the machine as much as possible and state the contamination status in a 'Declaration of Contamination'.

Busch will only accept machine accompanied by a signed, fully completed and legally binding "declaration of contamination", downloadable from the following link: *buschvacuum.com/declaration-ofcontamination*.



## Decommissioning



## 

#### Live wires.

#### **Risk of electrical shock!**

• Electrical installation work must only be executed by qualified personnel.



## 

#### Hot surface.

#### **Risk of burns!**

- Before doing anything that requires touching the machine, let it cool down first.
- Shut down the machine and lock against inadvertent start up.
- Disconnect the power supply.
- Turn off the water supply.
- Vent the connected lines to atmospheric pressure.
- Disconnect all connections.

If the machine is to be stored:

• See *Storage* [→ 11].

### 10.1 Dismantling and Disposal

- Drain and collect the oil.
- Make sure that no oil drips onto the floor.
- Drain and collect the cooling liquid.
- Make sure that no cooling liquid drips onto the floor.
- Separate special waste from the machine.
- Dispose of special waste in compliance with applicable regulations.
- Dispose of the machine as scrap metal.

## 11 Spare Parts

## NOTICE

Use of non-Busch genuine spare parts.

**Risk of premature failure!** 

#### Loss of efficiency!

• The exclusive use of Busch genuine spare parts and consumables is recommended for the correct functioning of the machine and to validate the warranty.

There are no standard spare parts kits available for this product.

If you require Busch genuine parts:

• Contact your Busch representative.

### 12

## Troubleshooting



## DANGER

Live wires.

**Risk of electrical shock!** 

• Electrical installation work must only be executed by qualified personnel.



## 

#### Hot surface.

**Risk of burns!** 

• Before doing anything that requires touching the machine, let it cool down first.

Problem	Possible Cause	Remedy
The machine does not start.	The motor is not supplied with the correct voltage.	• Check the power supply.
	The rotors are jammed or seized.	• Turn the screw rotors manu- ally from the rotor access plug (PMR).
		• Repair the machine (contact Busch).
	Solid foreign matter has en- tered the machine.	<ul> <li>Remove the solid foreign matter or repair the ma- chine (contact Busch).</li> </ul>
		• Install an inlet filter if neces- sary.
	A temperature sensor has	• Let the machine cool down.
	reached the switch point.	<ul> <li>See problem "The machine runs too hot".</li> </ul>
	Corrosion in the machine from	Repair the machine.
	remaining condensate.	<ul> <li>Check the process and fol- low the recommendation in case of Conveying Condens- able Vapours.</li> </ul>
	The motor is defective.	• Replace the motor.

Problem	Possible Cause	Remedy					
The machine does not reach the usual pressure on the suc-	Suction or discharge lines too long or section diameter too	• Use larger diameter or shorter lines.					
tion connection.	small.	• Seek advice from your local Busch representative.					
	Process deposits on the pump- ing components	• Flush the machine.					
	If an inlet screen or an inlet fil- ter is installed, it can be partial- ly clogged.	• Clean the inlet screen or re- place the inlet filter car- tridge.					
	The machine runs in the wrong direction.	<ul> <li>Check the direction of rotation, see Wiring Diagram Three-Phase Motor (Pump Drive) [→ 22].</li> </ul>					
	Internal parts are worn or damaged.	• Repair the machine (contact Busch).					
The machine runs very noisily.	Wrong oil quantity or unsuit- able oil type.	• Use one of the recommend- ed oils in the correct quanti- ty, see <i>Oil</i> [→ 40].					
	Defective gears, bearings or coupling element.	• Repair machine (contact Busch).					
The machine runs too hot.	Insufficient cooling.	<ul> <li>Make sure to comply with the cooling water require- ments, see Cooling Water Connection.</li> </ul>					
	Ambient temperature too high.	<ul> <li>Observe the permitted am- bient temperature, see Technical Data.</li> </ul>					
	Temperature of the process gases at the inlet too high.	<ul> <li>Observe the permitted gas inlet temperature, see Tech- nical Data.</li> </ul>					
	Oil level too low.	• Top up oil.					
The oil is black.	Oil change intervals are too long.	<ul> <li>Drain the oil and fill in new oil, see Oil Change [→ 29].</li> </ul>					
	The machine runs too hot.	• See problem "The machine runs too hot".					
	Internal parts are worn or damaged.	Repair the machine (contact Busch).					

For resolution of problems not listed in the troubleshooting table, please contact your Busch representative.

## 13 Technical Data

		NS 0070 C	NS 0160 C
Nominal pumping speed	m³/h	70 / 85	135 / 170
(50 Hz) / (60 Hz)	ACFM	41 / 50.0	79 / 94.2
Ultimate pressure	hPa (mbar)	3.0 · 10 <sup>-2</sup>	3.0 · 10 <sup>-2</sup>
	TORR	2.2 · 10 <sup>-2</sup>	2.2 · 10 <sup>-2</sup>
Nominal motor rating backing pump (50 Hz) / (60 Hz)	kW	4.0 / 4.4	5.5 / 6.6
Maximal intensity Y / Δ (50 Hz) / (60 Hz)	A	9.5 / 16.6 9.9 / 17.2	11.7 / 20.5 15.4 / 27
Operating voltage and nominal motor current (50 Hz)	Δ 200 / 230 / 255 V	15.9 / 16.6 / 20	21 / 20.5 / 25
	Y 346 / 400 / 440 V A	9.2 / 9.5 / 11.7	12.2 / 11.7 / 14.3
Operating voltage and nominal motor current	Δ 200 / 277 V	17.2 / 15.8	27 / 21
(60 Hz)	Y 346 / 480 V A	9.9 / 9.1	15.4 / 12.0
Nominal motor speed (50 Hz) / (60 Hz)	min-1	2840 / 3380	2870 / 3440
Sound pressure level (ISO 2151) KpA = 3 dB	dB(A)	62	68
Ambient temperature	°C	0 40	0 40
range	°F	32 104	32 104
Maximum allowable counter pressure at dis- charge	hPa (mbar)	200	200
Water consumption	l/min	≥ 3	≥3
Cooling water tempera- ture	°C	10 - 20	10 - 20
Cooling water pressure	bar	2 - 5	2 - 5
Nitrogen consumption	l/min	0 - 18	0 - 18
Nitrogen overpressure	bar	1.5	1.5
Oil capacity - Motor side	I	1.15	1.15
Oil capacity - Suction side	I	0.5	0.5
Cooling liquid capacity approx.	I	4	4
Weight approx.	kg	210	225

## 14 Cooling Liquid

	Zitrec <sup>®</sup> M (Ready-to-use)
Part number 5 L packaging	0831 563 469
Part number 20 L packaging	0831 238 761

**Zitrec**<sup>®</sup> **M** coolant (Cooling liquid) is ready-to-use and requires no additional water.


For more information, visit *www.arteco-coolants.com*.

15

### Oil

	YLC 250 B
ISO-VG	250
Oil Type	Synthetic
Part number 0.5 L packaging	0831 131 400
Part number 1 L packaging	0831 108 878
Part number 5 L packaging	0831 108 879

To find out which oil needs to be filled into the machine, please refer to the nameplate (NP).



## 16 EU Declaration of Conformity

This Declaration of Conformity and the CE-markings affixed to the nameplate are valid for the machine within the Busch scope of delivery. This Declaration of Conformity is issued under the sole responsibility of the manufacturer.

When this machine is integrated into a superordinate machinery the manufacturer of the superordinate machinery (this can be the operating company, too) must conduct the conformity assessment process for the superordinate machine or plant, issue the Declaration of Conformity for it and affix the CE-marking.

The manufacturer is determined by the serial number:

Serial number starts with CHM1...

Ateliers Busch S.A. Zone industrielle 2906 Chevenez Switzerland Serial number starts with **KRM1...** 

Busch Manufacturing Korea, Ltd. 189-51, Soicheon-ro, Majang-myun Icheon-si, Gyunggi-do, 467-813 Republic of Korea

declares that the machine: COBRA NS 0070 C; COBRA NS 0160 C  $\,$ 

fulfill(s) all the relevant provisions from EU directives:

- 'Machinery' 2006/42/EC
- 'Electromagnetic Compatibility' (EMC) 2014/30/EU
  - 'RoHS' 2011/65/EU Restriction of the use of certain hazardous substances in electrical and electronic equipment (incl. all related applicable amendments)

and comply(-ies) with the following harmonized standards that have been used to fulfill those provisions:

Standards	Title of the Standard
EN ISO 12100 : 2010	Safety of machinery - Basic concepts, general principles of design
EN ISO 13857 : 2019	Safety of machinery - Safety distances to prevent hazard zones being reached by the upper and lower limbs
EN ISO 2151 : 2008	Acoustics - Noise test code for compressors and vacuum pumps - Engineering method (grade 2)
EN 60204-1 : 2018	Safety of machinery - Electrical equipment of machines - Part 1: General requirements
EN IEC 61000-6-2 : 2019	Electromagnetic compatibility (EMC) - Generic standards. Immunity for industrial environments
EN IEC 61000-6-4 : 2019	Electromagnetic compatibility (EMC) - Generic standards. Emission standard for industrial environ- ments

Legal person authorized to compile the technical file and authorized representative in the EU (if Busch Dienste GmbH the manufacturer is not located in the EU): Schauinslandstr. 1 DE-79689 Maulburg

Chevenez, 19.12.2023

Christian Hoffmann General Manager Ateliers Busch S.A.

Jeihong Kim

Icheon-si, 19.12.2023

Jeihong Kim General Manager Busch Manufacturing Korea, Ltd

## 17 UK Declaration of Conformity

This Declaration of Conformity and the UKCA-markings affixed to the nameplate are valid for the machine within the Busch scope of delivery. This Declaration of Conformity is issued under the sole responsibility of the manufacturer.

When this machine is integrated into a superordinate machinery the manufacturer of the superordinate machinery (this can be the operating company, too) must conduct the conformity assessment process for the superordinate machine or plant, issue the Declaration of Conformity for it and affix the UKCA-marking.

The manufacturer is determined by the serial number:

Serial number starts with CHM1...

Ateliers Busch S.A. Zone industrielle 2906 Chevenez Switzerland Serial number starts with KRM1...

Busch Manufacturing Korea, Ltd. 189-51, Soicheon-ro, Majang-myun Icheon-si, Gyunggi-do, 467-813 Republic of Korea

declares that the machine: COBRA NS 0070 C; COBRA NS 0160 C

fulfill(s) all the relevant provisions from UK legislations:

- Supply of Machinery (Safety) Regulations 2008
- Electromagnetic Compatibility Regulations 2016
- Restriction of the use of certain hazardous substances in Electrical and Electronic Equipment Regulations 2012

and comply(-ies) with the following designated standards that have been used to fulfill those provisions:

Standards	Title of the Standard
EN ISO 12100 : 2010	Safety of machinery - Basic concepts, general principles of design
EN ISO 13857 : 2019	Safety of machinery - Safety distances to prevent hazard zones being reached by the upper and lower limbs
EN ISO 2151 : 2008	Acoustics - Noise test code for compressors and vacuum pumps - Engineering method (grade 2)
EN 60204-1 : 2018	Safety of machinery - Electrical equipment of machines - Part 1: General requirements
EN IEC 61000-6-2 : 2019	Electromagnetic compatibility (EMC) - Generic standards. Immunity for industrial environments
EN IEC 61000-6-4 : 2019	Electromagnetic compatibility (EMC) - Generic standards. Emission standard for industrial environ- ments

Legal person authorized to compile the technical file and importer in the UK (if the manufacturer Busch (UK) Ltd is not located in the UK): 30 Hortonwood Telford – UK

Chevenez, 19.12.2023

Christian Hoffmann General Manager Ateliers Busch S.A.

Icheon-si, 19.12.2023

Jeihong Kim

Jeihong Kim General Manager Busch Manufacturing Korea, Ltd

### Notes

	0	•	0	0	• •		•	0	•	• •	•	•	•	•	• •		0	٠	• •		0	• •	0	0	•	• •	•		•		0	0		• •
		•	0		• •		٠		•	• •	•	•		•	• •		•	•	• •			• •	0	•	•	• •	•	0			•	•	0	• •
					• •		•		•	• •					• •				• •				0			• •								• •
		•	0	0			•	0	•	• •	0	0		0			0		• •				0		0		•	0			•		0	• •
		•					•	•			•	•							• •						•									
																							0											
							•					•																						
-						-	-							-			-			-	-			-	-			-	-		-	-	-	
, in the second	, in the second	Ŭ					ů.				, in the second se	, in the second se				, in the second se		Č.		, in the second se	,		, in the second se	, in the second			, in the second se		, in the second	, in the second	, in the second se			
•		•	•	•	• •	•	•	•	•	• •	•	•	•	•	• •	•	•	•	• •	•	•	• •	0	•	•	• •		•	•		•	•	•	• •
•	•	•	0	•	• •	•	0	0	•	• •	•	•	•	0	• •	0	0	٠	• •	•	0	• •	0	0	•	• •	•	0	•	•	0	0	0	0 0
•		•	0	0	• •		•	0	•	• •	0	0	0	0	• •	0	0	•	• •		0	• •	0	•	•	• •	•	0	•	0	0	•	0	• •
•		•	0	0	0 0		0	0	•	• •		0		0	• •	0	0	•	• •		0	• •	0	0		• •		0	0		0	•		0 0
•	0	۰	0	0	• •	0	0	0	•	• •	0	•	0	0	• •	0	0	٠	• •	•	0	• •	0	0	0	• •	•	0	۰	0	0	0	0	• •
•	•	۰	0	•	• •		0	0	•	• •	•	•	0	•	• •		0	•	• •	•		• •	0	0	•	• •	•	•	•	•	0	٠	•	• •
•		•	0		• •		0	0	•	• •		0			• •		0	*	• •			• •	0	0		• •		0			0			• •
•	•	۰	0	0	• •	0	۰	0	•	• •	•	•	0	0	• •	0	0	٠	• •	•	0	• •	0	0	•	• •	۰	0	۰	•	۰	•	0	• •
•	•	٠	0	•	• •		0	•	•	• •	۰	•		•	• •		0	•	• •	٠		• •		0	•	• •			•			•		• •
۰		•			• •		0	0	•	• •		0			• •	0	0		• •			• •	0	•		• •		0	۰		0	٠		• •
•	•	•	0	•	• •		۰	0	•	• •	•	•	•	•	• •	•	0	٠	• •		•	• •	0	۰	•	• •	٠	0	٠	•	۰	٠	0	• •
•	•	•	0		• •		0	•	•	• •	•	•	•	•	• •		0	•	• •			• •		0	•	• •	•		•	•	0	•		• •
•		•	0		• •		0	0	•	• •	0	0		•	• •	0	0	•	• •			• •	0	•		• •		0	٠		0	٠		• •
•		•		0	• •		۰	0	•	• •	0	0		0	• •		0	•	• •			• •	0	•		• •	•	0	•		•	•	0	• •
•	•	•	0		• •		0	0	•	• •	•	•	•	•	• •		0	•	• •			• •		0	•	• •			•		0	•		• •
•		•	0		• •		0	0	•	• •	0	0		•	• •	0	0		• •		•		0	•		• •		0	•		0	•		• •
•		•			• •		•		•	• •	•	•		•	• •		•		• •			• •	0	•	•	• •			•		•	•		• •
		•	0		• •		•	0	•	• •	•	•	•	0	• •	0	0		• •		0	• •	0	0	•	• •	•	0	•		•	•	0	• •
		•			• •		•					•							• •															
		•			• •		0		•	• •		•					0		• •					0							0			• •
•	0	•	0	0	• •	•	•	0	•	• •	0	•	0	•	• •	•	0	•	• •	•	•	• •	0	•	0	• •	0	•	•	0	•	•	•	• •
		•			• •		•		•			0					0		• •				0					0			•			
		•					•					•																						
•									•		•	•	•	•			0							•	•		•	•	•		•	•		
•				•	• •																										•		-	
		•	•	•	• •	•	•	0	•			•					0					0 0	0	0		0 0								
	0	•	•	•	•••	•	•	•	•	• •	•	•	•	•	• •	•	0	•	• •	•	•	• •	•	•	•	• •	•	•	•					
	•	•	•	•	•••	•	•	•	•	• •	•	•	•	•	• •	•	0	•	• •	•	•	•••	•	•	•	• •	•	•	•	0	•	•	•	0 0
	•	•	•	•	• • • • • •	•	•	•	•	•••	•	•	•	•	•••	•	•	•	• •	•	0	•••	0	•	•	• • • •	•	•	•	•	•	•	•	· ·
	•	•	0 0 0	•	• • • • • • • •	0 0 0 0	•	•	•	· ·	•	0	•	•	• •	•	0	•	• • • • • •	•	•	· · ·	0	•	•	• • • • • •	•	•	•	•	•	•	•	• •
																						· · ·												
•	•	۰	•	•	• •	۰	٠	٠	•	• •	٠	۰	•	•	• •	۰	٠	٠	• •	۰	٠	• •	۰	٠	•	• •	•	•	٠	•	٠	٠	•	• •
•	0	0	•	•	• •	•	•	•	•	•••	0	•	•	•	• •	•	•	•	• •	•	•	• •	•	•	•	• •	•	0	•	•	•	•	•	• •
•	0	0	•	•	• •	•	0	0	•	• •	0	•	•	•	• •	0	0	•	• •	•	0	• •	0	•	•	• •	•	0	•	0	•	0	•	• •
•	0	0	0 0 0	•	• • • • • •	•	0 0 0	0 0 0	•	• • • • • •	•	0	•	•	• •	•	0 0 0	•	• • • • • •	•	0 0 0	• •	0 0 0	•	•	• •	•	0	•	•	0	•	•	• • • • • •
•	0	0 0 0	0 0 0	•	• • • • • •	0 0 0	0 0 0	0 0 0	0 0 0	• • • • • •	•	0 0 0	0 0 0	•	0 0 0 0 0 0	•	0 0 0	•	• • • • • •	•	0 0 0	• • • • • •	•	•	•	• • • • • •	0 0 0	0 0 0	0 0 0	•	0 0 0	•	• • • • • • • • • • • • • • • • • • • •	• • • • • •
•	•	•	0 0 0 0	•	• • • • • • • •	•	• • • •	•	•	• • • • • • • •	•	• • • •	•	•	• • • • • •	0	0 0 0 0	•	• • • • • • • •	•	0 0 0		•	•	•	• • • • • •	0 0 0 0	0 0 0 0	0 0 0 0	•	•	•	•	• • • • • • • •
•	•	•	0 0 0 0	• • • • • • • • • • • • • • • • • • • •		• • • •	0 0 0 0	• • • •	•		•	0 0 0 0	0 0 0 0	• • • • • • • • • • • • • • • • • • • •		0 0 0 0	0 0 0 0	0 0 0 0		0 0 0 0	•		•	•	•		• • • •	0 0 0 0	• • • •	•	•	0 0 0 0	•	
• • • • • • • • •	0 0 0 0 0	• • • •	0 0 0 0 0	•				• • • • • • • •			• • • •		0 0 0 0	• • • • •				• • • • • • • • • • • • • • • • • • • •		0 0 0 0			• • • • •	0 0 0 0 0	•					0 0 0 0	0 0 0 0	• • • • • • •		
• • • • • •	0 0 0 0 0	• • • • •	0 0 0 0 0	• • • • • • • • • • • • • • • • • • • •		0 0 0 0 0	0 0 0 0 0 0	0 0 0 0 0	•		• • • • •	0 0 0 0 0	0 0 0 0 0	• • • • • • • • • • • • • • • • • • • •						• • • • •				0 0 0 0 0	• • • • • • • • • • • • • • • • • • • •			0 0 0 0 0 0		•	• • • • •	• • • • • • • • • • • • • • • • • • • •	•	
•	0 0 0 0 0 0	• • • • •	0 0 0 0 0 0	• • • • • • • • • • • • • • • • • • • •				0 0 0 0 0 0 0			0 0 0 0 0 0 0		0 0 0 0 0	• • • • •						• • • • • •					• • • • •		0 0 0 0 0 0			•	• • • • •	• • • • • • • • • • • • • • • • • • • •	• • • • • •	
• • • • • • •	• • • • • •	• • • • • •	0 0 0 0 0 0	• • • • • • •				• • • • • • •					0 0 0 0 0	• • • • • • •		•		•						•	• • • • • • •		0 0 0 0 0 0 0 0			•	• • • • •			
•		• • • • • •	0 0 0 0 0 0 0	• • • • • • • •				• • • • • • • •						• • • • • • • •		•		•						•	• • • • • • • •					•	• • • • • • • •	•		
• • • • • • • •		• • • • • • • •		• • • • • • • •				• • • • • • • •					• • • • • • • •	• • • • • • • •											• • • • • • • • •					•	• • • • • • • •			
• • • • • • • •		• • • • • • • •		• • • • • • • •				• • • • • • • •					• • • • • • • •	• • • • • • • •											• • • • • • • • •						• • • • • • • •			
• • • • • • • •													•	• • • • • • • • •		· · · · ·									• • • • • • • • •						• • • • • • • • •			
													• • • • • • • • • • •												• • • • • • • • • • • •						• • • • • • • • •			
																								• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • •						• • • • • • • • •			
								• • • • • • • • • • • •																	• • • • • • • • • • • •						• • • • • • • • •			

# Busch Vacuum Solutions

With a network of over 60 companies in more than 40 countries and agencies worldwide, Busch has a global presence. In every country, highly competent local personnel delivers custom-tailored support backed by a global network of expertise. Wherever you are. Whatever your business. We are there for you.



Busch companies and Busch employees 🛛 🔵 Local representatives and distributors 🖉 🔮 Busch production site

# www.buschvacuum.com